	er ID 60841 5, 2010 10:28:52 AM				,					Page 1
tem ID: Revision ID: tem Name: Start Date: Required Date: Reference:	DSK081 D2940-1 TURNING DETAIL 7/26/2010 Start Qty: 4.00 7/30/2010 Req'd Qty: 4.00		Accept	Cust Item II			Se	etup Star Stop		
Approvals:	Process Plan: QC:	Date://0-7-30			ite:	-	R	un Star Stop		
equence ID/ Vork Center II Draw Nbr	Operation D Description Revision Nbr		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
DSK081	Rev A MORI SEIKI CNC L	• ATHE LARGE	0.00)						
Mill III III III III III III III III III	Memo	nk as per Folio FA079	0.00	10/08/03			<u></u>			1
10 QC Quality Control	QC2- Inspect parts of Memo	ff machine FAI/FAIB	0.00 0.00	10/08/03				-	· · · · · · · · · · · · · · · · · · ·	
20 QC	QC8- Inspect parts - : Memo	second check	0.00 M	10.8.4	Y		6		· · · · · · · · · · · · · · · · · · ·	
Quality Control									į.	

.

Dart	Aeros	space	Ltd
------	--------------	-------	-----

Dart Ae	rospace Ltd									
W/O:			WORK ORDER	CHANGES						
DATE	STEP	PR	OCEDURE CHANGE	•	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						·				
Part No):	PAR #:	Fault Category:	NCR:	Yes	No DQ	A:	Date: _		
Resolution: _		on:	Disposition:		QA: N/C Closed:					
NCR:		,	WORK ORDER NON-COM	IFORMANCE ((NC	R)		,		

NCR:			WORK OR	DER NON-CONFORMAN	CE (NCR)		•	
· · · · · · · · · · · · · · · · · · ·		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		· · · · · · · · · · · · · · · · · · ·	·					
								

							!						!
Work Ord Monday, July 20											i. I	Page 2	+ · · · · · · · · · · · · · · · · · · ·
Item ID: Revision ID:	DSK081			Accept				iiii s	Setup	Start			+
Item Name: Start Date: Required Date: Reference:	7/26/2010	RNING DETAIL Start Qty: 4.00 Req'd Qty: 4.00			Cust Item I Customer:	D:				Stop			1
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		nte:		F	₹un	Start Stop			i
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Tool ID		Plan Code	Accept Qty	Rej Qty		eject umber	Insp. Stamp	→
130 Packaging Packaging		Packaging Memo Identify and	Stock in Kanban□Locatio	0.00	uf 10.8.	4		(C))	<u>-</u>			- !
		QC21- Final Inspection -	Work Order Release	0.00	· : :					,	10/08	105	* *
QC Quality Control		Memo		0.00			} 			<u>'</u>	int 1	0 - 08	C-1

Dart Aerospace Ltd

	-									
W/O:				W	ORK ORDER CHAN	IGES				
DATE	STEP		PRO	CEDURE CHANGE By Date Qty					Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·	••							
								\$. S		
		·	\							
			·							
Part No	:	PA		Fault Cate	egory:	NC	R: Yes I	lo DQA:	Date: _	<u></u>
	R	esolution:	- · · · - · · - · ·	Disposition	on:	QA	N/C Clo	sed:	Date:	
NCR:			V	VORK ORD	ER NON-CONFOR	MANCE	(NCR)			
DATE	STEP	Description of		Section B		Verification	Approval	Approval		
DATE	SIEP	Section A		Initial Chief Eng	Action Descriptio Chief Eng	n	Sign & Date	Section C	Chief Eng	QC Inspector
					,					
										_
	.,		• • • • • • • • • • • • • • • • • • • •							
									1	

Picklist Print Page Monday, July 26, 2010 10:28:56 AM Work Order ID: 60841 Parent Item: DSK081 Parent Item Name: D2940-1 TURNING DETAIL Required Date: 7/30/2010 Start Date: 7/26/2010 Start Qty: 4.00 Required Qty: 4.00 Comments: IPP rev A. 08.03.13 new issue EC Component Item ID/ Replacement Mfg/ Primary **Unit of** Qty per Kit Total Bin Last Qty on Route Qty Date Status Item Name Item ID Item Location Location Seq ID Measure Hand Purch Issued Qty Issued D6104-007 Manufactured No Each 10.0000 Round Billet, 17-4 **Location** Loc Qty Loc Code MAT43 10 5/ 10/08/02 -- 53752 10

Dart Ae	rospace	e Ltd 📆		•						•
W/O:		1 de la companya della companya della companya de la companya della companya dell	WOI	RK ORDER CH	ANGES			i		
DATE	STEP	PR	OCEDURE CHAN	GE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
			' v ² .				·		19 19 19 19 19	
,					2					
Part No):	PAR #:	Fault Categ	ory:	NC	R: Yes	No DQA :		Date: _	·
	R	esolution:	Disposition	`	Q/	A: N/C Cld	sed:	_	Date: _	
NCR:	,		WORK ORDE	R NON-CONFO	ORMANC	E (NCR)	,		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descri	Section B ption	Sign & Date	Verificat Section		Approval Chief Eng	Approva QC Inspecto
		÷								
					-					

DART AEROSPACE LTD	Work Order:	40841
Description: Turning Detail for D2940-1	Part Number:	DSK081
Inspection Dwg: DSK081 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION DIMENSION SHEET


A-10				Article	Proto	Actual Dim	ensions] .
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	5	
				Lathe Section	n 🗥	<u> </u>		<u> </u>	
Α	3.211	3.216		13.214	13.213	13.213	13.23	3,215	3.6
В	4.946	4.966		4.960	4.957	4.957	4.957	4.957	4.
С	0.718	0.738		726	,726	- 726	.726	-726	7
D	0.090	0.110		.100	.100	-100	100	.100	1.1
E	3.564	3.584		3.575	3.875	3.574		3,574	3.6
F	0.022	0.042		.032	.032	-032	-032	-038	3.5
G	3.444	3.464		3,455	3,464	7 454	3 4545	3.454	3.5
Н	0.112	0.132		120	.120	:121	-120	-118	- 11
ī	2.170	2.190		2./80	2,180	2/80	2/80	2180	24
J	4.451	4.471		4.460	4-460	4.460	4.459	4.459	14
K	0.413	0.433		1.427	.424.	.424	.424	1.424	
L	0.913	0.933		927	. 924	-924	.924	. 924	. <i>i</i>
М									
N									
0									
P									
	Measured	hv:	\ / \i		·	Date:	10/08/	á2	7
	weasureu	<u></u>	1 / VL			Date.	10000	<u> </u>	اك
	Audited	by: Ush)		·	Date:	10.8	.4	1
		7				J	·		_
rotot	type Approv	/al:				Date:]
ev	Date (Change				Re	vised by	Approv <i>e</i> d	1
		New Issue					/JLM ON		1

Dail AcidSbace Liu	Dart	Aeros	pace	Ltd
--------------------	-------------	--------------	------	-----

W/O:				W	ORK ORDER CHANG	ES					
DATE	STEP		PRO	OCEDURE CH	ANGE	Ву	C	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•						ļ					·
			·								
			•								
Part No	:		PAR #:	Fault Ca	tegory:	_ NCR: Y	es No	DQ.	A :	Date: _	
	R	esol	tion:	Disposit	ion:	QA: N/C	Close	ed:		Date: _	
NCR:				WORK OR	DER NON-CONFORM	ANCE (N	CR)	·			
DATE STEP			Description of NC			tion B			cation		Approval
DATE			Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti	ion C	Chief Eng	QC Inspector
		E :									
				·							


H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE





PE E SED

03.03.07 **NEW ISSUE** В 03.06.24 ADDED 4.956 DIMENSION



Copyright © 2003 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART-AEROSPACE LTD.

Dart Ae	rospace	e Ltd					•			
W/O:				WO	RK ORDER CHANGI	ES	•		<u> </u>	
DATE	STEP		PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
									•	
							-			
	}									
Part No	:		PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolu	tion:	Disposition	n:	_ QA: N/C C	osed:			<u> </u>
NCR:			,	WORK ORDE	ER NON-CONFORMA	NCE (NCF	?)			*
			Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	STEP		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	k Sect	tion C	Chief Eng	
										, jak
									•	

H:\fFORMS\Quality Assurance \approved QA\NCRWO RevE